

VIREO / Day2 / Flight2

TEST: Testing control law, injecting chirps.

RESULT: First attempt at closing the loop using estimates of gains. Calibration of IMU and magnetometer. The tail was damaged upon landing.